



State of Colorado  
Oil and Gas Conservation Commission  
DEPARTMENT OF NATURAL RESOURCES

RECEIVED  
FEB - 2 99  
COGCC

SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (back of this form).

ET	OE	PR	ES
----	----	----	----

1. OGCC Operator Number: 06495	4. Contact Name & Phone
2. Name of Operator: BARRETT RESOURCES CORP.	Duane Zavadil
3. Address: 1515 Arapahoe St., Tower 3, Ste. #1000	No: (303)572-3900
City: Denver State: CO Zip: 80202	Fax: (303) 629-8265

Complete the  
Attachment Checklist

	Oper	OGCC
Survey Plat		
Directional Survey		
Surface Equipment		
Technical Information Page		
Other		

5. API Number: 05-045-6709	6. OGCC Lease No:
7. Well Name: GV 65-2	Number:
8. Location (QtrQtr, Sec, Twp, Rng, Meridian): NWNW Sec. 2, T7S R95W, 6th P.M.	
9. County: Garfield	10. Field Name: Grand Valley
11. Federal, Indian or State Lease Number:	

12. General Notice

☐ Change well name from \_\_\_\_\_ to \_\_\_\_\_ Effective Date: \_\_\_\_\_

☐ Change of location from \_\_\_\_\_ to \_\_\_\_\_  
Attach new survey plat.

☐ Abandoned Location. Is site ready for inspection? ☐ Yes ☐ No Effective Date: \_\_\_\_\_  
Was location ever built? ☐ Yes ☐ No Permit No: \_\_\_\_\_

☐ Well first shut in or temporarily abandoned \_\_\_\_\_ Notice of continued shut-in status.  
Has production equipment been removed from Site? ☐ Yes ☐ No  
MIT required if shut in longer than two years. Date of last MIT: \_\_\_\_\_

☐ Well resumed production on \_\_\_\_\_

☐ Request for Confidential Status (6 months).

☐ Final reclamation will commence approximately on \_\_\_\_\_

☐ Final reclamation is completed and site is ready for inspection. Attach technical page describing final reclamation procedures per \_\_\_\_\_

☐ Change of Operator (prior to drilling). Effective Date: \_\_\_\_\_ Plugging bond: ☐ Blanket ☐ Individual

☐ Spud Date \_\_\_\_\_

13. Technical Engineering/Environmental Notice

<input type="checkbox"/> Notice of Intent Approximate Start Date: _____	<input checked="" type="checkbox"/> Report of Work Done Date work Completed: December, 1997
--	--

Details of work must be described in full on Technical Informtion Page (Page 2 must be submitted).

<input type="checkbox"/> Commingle Zones	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E& P Waste Disposal
<input type="checkbox"/> Intent to Recomplete	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Convert Well to Injection (in an Approved Secondary Project)	<input type="checkbox"/> New Pit
<input type="checkbox"/> Reservoir Stimulation	<input type="checkbox"/> Additional Source Leases for Water Disposal Well	<input type="checkbox"/> Landfarming
<input type="checkbox"/> Perforating/Perfs Added	<input type="checkbox"/> Other: _____	<input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases
Gross Interval Changed? <input type="checkbox"/> Yes <input type="checkbox"/> No		

A111854  
B111853  
ext. 4194  
KD

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Duane Zavadil  
Signed: \_\_\_\_\_ Title: Envrionmental Manager Date: 01/30/98

OGCC Approved: \_\_\_\_\_ Title: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE

1. OGCC Operator Number:	06495	2. API Number:	05-045-6709
3. Name of Operator:	BARRETT RESOURCES CORP.		
4. Well Name:	GV 65-2	Number:	
5. Location (QtrQtr, Sec, Twp, Rng, Meridian):	NWNW Sec. 2, T7S R95W, 6th P.M.		

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within thirty (30 days of work) completed as a "subsequent" report and must accompany Form 4, Page 1.

FOR OGCC USE ONLY

ET	OE	PR	ES
----	----	----	----

6.

DESCRIBE PROPOSED OR COMPLETED OPERATIONS

Concrete vaults used for storage of produced water were found to leak when tested.  
Vaults were replaced with an 80 bbl fiberglass water tank.