



State of Colorado
Oil and Gas Conservation Commission
DEPARTMENT OF NATURAL RESOURCES

RECEIVED
FEB -2 98
COGCC

SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (back of this form).

ET	OE	PR	ES
----	----	----	----

1. OGCC Operator Number: 06495	4. Contact Name & Phone
2. Name of Operator: BARRETT RESOURCES CORP.	Duane Zavadil
3. Address: 1515 Arapahoe St., Tower 3, Ste. #1000	No: (303)572-3900
City: Denver State: CO. Zip: 80202	Fax: (303) 629-8265

Complete the
Attachment Checklist

	Oper	OGCC
Survey Plat		
Directional Survey		
Surface Equipment		
Technical Information Page		
Other		

5. API Number: 05-045-6729	6. OGCC Lease No:
7. Well Name: GV 45-34	Number:
8. Location (QtrQtr, Sec, Twp, Rng, Meridian): NWSW Sec. 34, T6S R95W, 6th P.M.	
9. County: Garfield	10. Field Name: Grand Valley
11. Federal, Indian or State Lease Number:	

12. General Notice

☐ Change well name from _____ to _____ Effective Date: _____

☐ Change of location from _____ to _____
Attach new survey plat.

☐ Abandoned Location. Is site ready for inspection? ☐ Yes ☐ No Effective Date: _____
Was location ever built? ☐ Yes ☐ No Permit No: _____

☐ Well first shut in or temporarily abandoned _____ Notice of continued shut-in status.
Has production equipment been removed from Site? ☐ Yes ☐ No
MIT required if shut in longer than two years. Date of last MIT: _____

☐ Well resumed production on _____

☐ Request for Confidential Status (6 months).

☐ Final reclamation will commence approximately on _____

☐ Final reclamation is completed and site is ready for inspection. Attach technical page describing final reclamation procedures per _____

☐ Change of Operator (prior to drilling). Effective Date: _____ Plugging bond: ☐ Blanket ☐ Individual

☐ Spud Date _____

13. Technical Engineering/Environmental Notice

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Report of Work Done
Approximate Start Date: _____	Date work Completed: December, 1997

Details of work must be described in full on Technical Informtion Page (Page 2 must be submitted).

<input type="checkbox"/> Commingle Zones	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E & P Waste Disposal
<input type="checkbox"/> Intent to Recomplete	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Convert Well to Injection (in an	<input type="checkbox"/> New Pit
<input type="checkbox"/> Reservoir Stimulation	Approved Secondary Project)	<input type="checkbox"/> Landfarming
<input type="checkbox"/> Perforating/Perfs Added	<input type="checkbox"/> Additional Source Leases for	<input type="checkbox"/> Status Update/Change of
Gross Interval Changed?	Water Disposal Well	Remediation Plans for Soils and
<input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Other: _____	Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Duane Zavadil	Title: Envrionmental Manager	Date: 01/30/98
Signed: <u>Duane Zavadil</u>		

OGCC Approved: _____	Title: _____	Date: _____
----------------------	--------------	-------------

CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE

FOR OGCC USE ONLY

1. OGCC Operator Number:	06495	2. API Number:	05-045-6729
3. Name of Operator:	BARRETT RESOURCES CORP.		
4. Well Name:	GV 45-34	Number:	
5. Location (QtrQtr, Sec, Twp, Rng, Meridian):	NWSW Sec. 34, T6S R95W, 6th P.M.		
This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within thirty (30 days of work) completed as a "subsequent" report and must accompany Form 4, Page 1.			

ET	OE	PR	ES
----	----	----	----

6.

DESCRIBE PROPOSED OR COMPLETED OPERATIONS

Concrete vaults used for storage of produced water were found to leak when tested.
Vaults were replaced with an 80 bbl fiberglass water tank.