

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
05/14/2015

Document Number:
675201571

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
	334436	334436	CONKLIN, CURTIS		

Operator Information:

OGCC Operator Number: <u>16800</u>
Name of Operator: <u>DELTA PETROLEUM CORP NDBA PAR PETROLEUM</u>
Address: <u>800 GESSNER SUITE 875</u>
City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77024</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:

QtrQtr: <u>SWNE</u>	Sec: <u>29</u>	Twp: <u>9S</u>	Range: <u>93W</u>
---------------------	----------------	----------------	-------------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/14/2013	668500316			SATISFACTORY		Pass	No

Inspector Comment:

Form 2A and well permits in process. Location has been staked.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301473	WELL	AL	10/13/2011	LO	077-09983	NVEGA 29-414	AL
301474	WELL	AL	10/13/2011	LO	077-09984	NVEGA 29-411	AL
301475	WELL	AL	10/14/2011	LO	077-09985	NVEGA 29-312	AL
301476	WELL	AL	10/13/2011	LO	077-09986	NVEGA 29-311	AL
301477	WELL	AL	10/14/2011	LO	077-09987	NVEGA 29-422	AL
301478	WELL	AL	10/14/2011	LO	077-09988	NVEGA 29-314	AL
301481	WELL	AL	10/14/2011	LO	077-09989	NVEGA 29-211	AL
301482	WELL	AL	10/14/2011	LO	077-09990	NVEGA 29-212	AL
301483	WELL	AL	10/13/2011	LO	077-09991	NVEGA 29-213	AL
301484	WELL	AL	10/13/2011	LO	077-09992	NVEGA 29-321	AL

301485	WELL	AL	10/13/2011	LO	077-09993	NVEGA 29-214	AL	<input type="checkbox"/>
301486	WELL	AL	10/13/2011	LO	077-09994	NVEGA 29-412	AL	<input type="checkbox"/>
301487	WELL	AL	10/13/2011	LO	077-09995	NVEGA 29-221	AL	<input type="checkbox"/>
301488	WELL	AL	10/13/2011	LO	077-09996	NVEGA 29-324	AL	<input type="checkbox"/>
301489	WELL	AL	10/13/2011	LO	077-09997	NVEGA 29-331	AL	<input type="checkbox"/>
301490	WELL	AL	10/13/2011	LO	077-09998	NVEGA 29-323	AL	<input type="checkbox"/>
301491	WELL	AL	10/13/2011	LO	077-09999	NVEGA 29-322	AL	<input type="checkbox"/>
301492	WELL	AL	10/14/2011	LO	077-10000	NVEGA 29-421	AL	<input type="checkbox"/>
301493	WELL	AL	10/14/2011	LO	077-10001	NVEGA 29-222	AL	<input type="checkbox"/>
301494	WELL	AL	10/14/2011	LO	077-10002	NVEGA 29-224	AL	<input type="checkbox"/>
301495	WELL	AL	10/13/2011	LO	077-10003	NVEGA 29-232	AL	<input type="checkbox"/>
301496	WELL	AL	10/13/2011	LO	077-10004	NVEGA 29-223	AL	<input type="checkbox"/>
301497	WELL	AL	10/13/2011	LO	077-10005	NVEGA 29-413	AL	<input type="checkbox"/>
301498	WELL	AL	10/13/2011	LO	077-10006	NVEGA 29-313	AL	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334436

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:	Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
No evidence of construction at time of inspection.	conklinc	05/14/2015