



photo 1: Center of the location facing north.



photo 2: Center of the location facing west.



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.



photo 5: Area on the location with sparse weed growth.



photo 6: Evidence of manure applied to the location.



photo 7: Weed growth (kochia, Russian thistle) throughout the location.



photo 8: South side of the location facing north.



photo 9: Surrounding vegetation nearby the location.



photo 10: Surrounding vegetation nearby the location.