



photo 1: Southwest corner of the location facing northeast towards the location.



photo 2: Pipe riser remains on the location (Lat/Long: 38.38739, -102.69977).



photo 3: Area with no vegetation growth appears to have rows from possible seeding and manure applied.



photo 4: Weed growth (kochia, Russian thistle, pennycress) throughout the location.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.