



photo 1: Facing north towards the location.



photo 2: Early stage annual (field pennycress) weed growing throughout the location.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.



photo 7: Perrinial grasses are beginning to establish throughout the location..



photo 8: Noticed a few thistle (scotch) plants growing on the location.



photo 11: Facing north at the location after mowing.



photo 12: Southwest corner of the location after mowing.