

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/15/2015

Document Number:

674701421

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335200	335200	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

**Compliance Summary:**QtrQtr: NENW Sec: 28 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/22/2015	674700879			<b>ACTION REQUIRED</b>			No
05/15/2014	663903199			SATISFACTORY			No
01/22/2014	663902681			SATISFACTORY	I		No

**Inspector Comment:**Follow up inspection to inspection doc # 674700879. Corrective actions have been addressed.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
252	WELL	PR	03/27/2009	GW	045-15460	N. PARACHUTE MF02B C28 696	PR	<input checked="" type="checkbox"/>
253	WELL	PR	04/17/2009	GW	045-15461	N. PARACHUTE MF01A C28 696	PR	<input checked="" type="checkbox"/>
254	WELL	PR	04/17/2009	GW	045-15462	N. PARACHUTE MF01D C28 696	PR	<input checked="" type="checkbox"/>
255	WELL	PR	04/30/2009	GW	045-15463	N. PARACHUTE MF01C C28 696	PR	<input checked="" type="checkbox"/>
256	WELL	PR	03/31/2009	GW	045-15464	N. PARACHUTE MF02A C28 696	PR	<input checked="" type="checkbox"/>
258	WELL	PR	01/31/2009	GW	045-15465	N. PARACHUTE MF02D C28 696	PR	<input checked="" type="checkbox"/>
259	WELL	PR	04/14/2009	GW	045-15466	N. PARACHUTE MF01B C28 696	PR	<input checked="" type="checkbox"/>
260	WELL	PR	01/20/2009	GW	045-15467	N. PARACHUTE MF02C C28 696	PR	<input checked="" type="checkbox"/>
291912	WELL	PR	04/14/2009	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

291915	WELL	PR	01/19/2009	GW	045-14552	N. PARACHUTE MF10A-21C28 696	PR	<input checked="" type="checkbox"/>
291916	WELL	PR	04/15/2009	GW	045-14551	N. PARACHUTE MF10B-21C28 696	PR	<input checked="" type="checkbox"/>
291918	WELL	PR	04/17/2009	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR	<input checked="" type="checkbox"/>
291920	WELL	PR	04/30/2009	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR	<input checked="" type="checkbox"/>
292039	WELL	PR	04/14/2009	GW	045-14554	N. PARACHUTE MF15B-21C28696	PR	<input checked="" type="checkbox"/>
293694	WELL	PR	04/17/2009	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR	<input checked="" type="checkbox"/>
293695	WELL	PR	04/17/2009	GW	045-15109	N. PARACHUTE MF16C-21 C28 69	PR	<input checked="" type="checkbox"/>
425557	PIT		09/19/2011		-	C28 696		<input type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: 970-285-2615

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	16	SATISFACTORY	Gas lift		
Plunger Lift	16	SATISFACTORY			
Gas Meter Run	16	SATISFACTORY			
Ancillary equipment		SATISFACTORY	Chemical containers		

<b>Facilities:</b>		New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	<100 BBLS	STEEL AST	,	
S/A/V:	SATISFACTORY		Comment: No ahrs id on tank		
Corrective Action:				Corrective Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) 80 bbl _____					
Other (Type) _____					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<b>Venting:</b>					
Yes/No		Comment			
NO					
<b>Flaring:</b>					
Type	Satisfactory/Action Required		Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335200

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 252 Type: WELL API Number: 045-15460 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 253 Type: WELL API Number: 045-15461 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 254 Type: WELL API Number: 045-15462 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID:	255	Type:	WELL	API Number:	045-15463	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	256	Type:	WELL	API Number:	045-15464	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	258	Type:	WELL	API Number:	045-15465	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	259	Type:	WELL	API Number:	045-15466	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	260	Type:	WELL	API Number:	045-15467	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291912	Type:	WELL	API Number:	045-14553	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291915	Type:	WELL	API Number:	045-14552	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291916	Type:	WELL	API Number:	045-14551	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291918	Type:	WELL	API Number:	045-14550	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	291920	Type:	WELL	API Number:	045-14549	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	292039	Type:	WELL	API Number:	045-14554	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Facility ID:	293694	Type:	WELL	API Number:	045-15108	Status:	PR	Insp. Status:	PR

**Producing Well**Comment: **Producing well**

Facility ID: 293695 Type: WELL API Number: 045-15109 Status: PR Insp. Status: PR

**Producing Well**Comment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass					
		Ditches	Pass			
		Compaction	Pass			
		Check Dams	Pass			
Hydro Mulch	Pass					
				MHSP	Pass	

Inspector Name: LONGWORTH, MIKE

Check Dams	Pass				
Slope Roughening	Pass				
		Gravel	Pass		

S/A/V: SATISFACTOR  
Y  
Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Follow up inspection to inspection doc # 674700879. Corrective actions have been addressed.	longworm	05/15/2015