



photo 1: Well sign, Keyton 41-7V



photo 2: Facing west towards the location.



photo 3: A Bull thistle plant was found on the location which is a List B noxious weed.



photo 4: Facing towards the east side of the location. Noticed metal tin debris at this area.