



Photo 1. View of Russian knapweed (*Acroptilon repens*) plants within the northern portion of the project area. Russian knapweed is the lighter green-blue plant in the mid- and background.



Photo 2. View of erosional channel forming within the northeastern portion of the project area.



Photo 3. View from northeastern corner of project area facing center.



Photo 4. View of western portion of project area. Straw mulch appears to be helping to stabilize the slopes.