

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
05/21/2015Document Number:
674701429Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335753	335753	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

Compliance Summary:QtrQtr: SENW Sec: 9 Twp: 6S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/03/2014	674700686			SATISFACTORY			No
12/03/2014	674700683			ACTION REQUIRED			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
210957	WELL	PR	10/13/1990	GW	045-06715	MOBIL 1-9-95	PR	<input checked="" type="checkbox"/>
279236	WELL	PR	09/28/2006	GW	045-11019	AP 22-9-695	PR	<input checked="" type="checkbox"/>
279360	PIT	AC	08/16/2005		-	AP 22-9 695	AC	<input type="checkbox"/>
290188	WELL	PR	04/16/2007	GW	045-14043	AP 23-9-695	PR	<input checked="" type="checkbox"/>
290189	WELL	PR	10/09/2014	GW	045-14042	AP 422-9-695	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Washing rills starting down roadway.		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 970-285-9377

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PIT	SATISFACTORY			
WELLHEAD	SATISFACTORY			
SEPARATOR	SATISFACTORY			
TANK BATTERY	SATISFACTORY			

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	1	SATISFACTORY	Chemical container at wells		
Gas Meter Run	1	SATISFACTORY			
Bird Protectors	5	SATISFACTORY			
Plunger Lift	4	SATISFACTORY			
Dehydrator	1	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,

S/A/V: SATISFACTORY

Comment: _____

Corrective Action: _____

Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Inspector Name: LONGWORTH, MIKE

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Corrective Action		Corrective Date	
Comment			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,

S/A/V:	SATISFACTORY	Comment:	045-2075-001
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Corrective Action		Corrective Date	
Comment			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	,

S/A/V:	SATISFACTORY	Comment:	045-2075-001
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
YES	Bradens open to vent.

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335753

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 210957 Type: WELL API Number: 045-06715 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID: 279236 Type: WELL API Number: 045-11019 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 290188 Type: WELL API Number: 045-14043 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 290189 Type: WELL API Number: 045-14042 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Pass			
				MHSP	Pass	
		Ditches	Pass			

Inspector Name: LONGWORTH, MIKE

Berms	Pass					
Ditches	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: Washing rills starting down roadway.

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	279360	1433064	