

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/26/2015

Document Number:

675201601

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	295080	334533	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		chris_clark@oxy.com	

Compliance Summary:QtrQtr: SESW Sec: 11 Twp: 9S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/03/2011	200317466	SR	PR	ACTION REQUIRED			Yes
07/16/2010	200271231	PR	PR	SATISFACTORY			No
03/02/2010	200235834	PR	PR	SATISFACTORY			No
02/11/2009	200203694	PR	PR	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285897	WELL	PR	01/01/2011	GW	077-09110	MCDANIEL 11-11	PR	<input checked="" type="checkbox"/>
285898	WELL	PR	11/20/2008	GW	077-09111	MCDANIEL FED. 11-13	PR	<input checked="" type="checkbox"/>
285900	WELL	PR	01/01/2011	GW	077-09112	MCDANIEL FED. 11-5	PR	<input checked="" type="checkbox"/>
285901	WELL	PR	01/01/2011	GW	077-09113	MCDANIEL FED. 11-6	PR	<input checked="" type="checkbox"/>
285902	WELL	PR	04/16/2007	GW	077-09114	MCDANIEL FED. 11-12	PR	<input checked="" type="checkbox"/>
294698	WELL	PR	01/24/2011	GW	077-09502	MCDANIEL 11-14B	PR	<input checked="" type="checkbox"/>
295074	WELL	AL	10/11/2012	LO	077-09556	McDaniel 11-11A	AL	<input type="checkbox"/>
295075	WELL	AL	10/11/2012	LO	077-09557	McDaniel 11-11C	AL	<input type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

295076	WELL	AL	10/11/2012	LO	077-09558	McDaniel 11-11B	AL	<input type="checkbox"/>
295077	WELL	PR	09/26/2008	GW	077-09559	MCDANIEL FEDERAL 11-12C	PR	<input checked="" type="checkbox"/>
295080	WELL	PR	03/17/2009	GW	077-09560	MCDANIEL FEDERAL 11-13C	PR	<input checked="" type="checkbox"/>
295081	WELL	AL	10/11/2012	LO	077-09561	McDaniel 11-14A	AL	<input type="checkbox"/>
295381	WELL	AL	10/11/2012	LO	077-09573	McDaniel Federal 11-13B	AL	<input type="checkbox"/>
295382	WELL	AL	07/09/2012	LO	077-09574	McDaniel Federal 11-12A	AL	<input type="checkbox"/>
295383	WELL	AL	10/11/2012	LO	077-09575	McDaniel Federal 11-13A	AL	<input type="checkbox"/>
295384	WELL	AL	10/11/2012	LO	077-09576	McDaniel Federal 11-12B	AL	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: **970-248-0497**

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	1	SATISFACTORY	Chem unit w/ containment		

Inspector Name: CONKLIN, CURTIS

Bird Protectors	3	SATISFACTORY			
Vertical Heated Separator	7	SATISFACTORY			
Plunger Lift	8	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
METHANOL	1	1000 GAL	STEEL AST	,

S/A/V: SATISFACTORY	Comment:
---------------------	----------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action	Corrective Date
-------------------	-----------------

Comment	Same
---------	------

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST	,

S/A/V: SATISFACTORY	Comment: Airs ID 077-0481-001
---------------------	-------------------------------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment	
---------	--

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 295080

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 285897 Type: WELL API Number: 077-09110 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285898 Type: WELL API Number: 077-09111 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285900 Type: WELL API Number: 077-09112 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285901 Type: WELL API Number: 077-09113 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285902 Type: WELL API Number: 077-09114 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 294698 Type: WELL API Number: 077-09502 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295077 Type: WELL API Number: 077-09559 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295080 Type: WELL API Number: 077-09560 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Inspector Name: CONKLIN, CURTIS

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Inspector Name: CONKLIN, CURTIS

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					
Compaction	Pass	Culverts	Pass			
Retention Ponds	Pass					
Berms	Pass	Compaction	Pass			
Ditches	Pass	Check Dams	Pass			

S/A/V: SATISFACTOR
Y _____ Corrective Date: _____

Comment: Erosion present on north side of location behind tanks. Evidence of stormwater run on to location.

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT