

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

 Inspection Date:
05/26/2015

 Document Number:
668603495

 Overall Inspection:
SATISFACTORY
FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | 435984 | 435983 | QUINT, CRAIG | 2A Doc Num: | |

Operator Information:OGCC Operator Number: 10422Name of Operator: PRONGHORN OPERATING LLCAddress: 8400 E PRENTICE AVENUE #1000City: GREENWOOD State: CO Zip: 80111

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------------|---------|
| Kuenzler, Zane | 720-261-2019 | zanekuenzler@kfrcorp.com | |

Compliance Summary:QtrQtr: SWNE Sec: 5 Twp: 14S Range: 44W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 08/01/2014 | 668602980 | DG | PR | SATISFACTORY | I | | No |
| 03/19/2014 | 668602314 | DG | DG | SATISFACTORY | | | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 435984 | WELL | PR | 04/24/2014 | OW | 017-07782 | Pepper 1 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|-------------------------|----------------------|---------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: <u>1</u> | Electric Motors: <u>1</u> |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: <u>1</u> |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: <u>2</u> | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------------------------|-------------------|------|
| Access | SATISFACTORY | DIRT ROAD THROUGH PASTURE | | |

Inspector Name: QUINT, CRAIG

| Signs/Marker: | | | | |
|----------------------|------------------------------|----------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| BATTERY | SATISFACTORY | LEASE SIGN BY TANKS | | |
| WELLHEAD | SATISFACTORY | LEASE SIGN BY UNIT | | |
| TANK LABELS/PLACARDS | SATISFACTORY | METAL SIGNS BY TANKS | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Equipment: | | | | | |
|---------------------|---|------------------------------|--------------------------------|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Pump Jack | 1 | SATISFACTORY | 228 CAPROCK | | |
| Ancillary equipment | 2 | SATISFACTORY | ELEC PANEL, CATHOTIC RECTIFIER | | |
| Prime Mover | 1 | SATISFACTORY | ELEC MOTOR | | |
| FWKO | 1 | SATISFACTORY | | | |

| Facilities: | | | | |
|-----------------------------------|---|----------------|----------------|-----------------------|
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS |
| CRUDE OIL | 2 | 300 BBLS | FIBERGLASS AST | 38.863970,-102.362950 |
| S/A/V: SATISFACTORY | Comment: SHARED BERMS WITH HARLEY 1 BATTERY | | | |
| Corrective Action: | | | | Corrective Date: |

| Paint | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

| Berms | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| NO | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 435984

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** SATISFACTORY **Comment:** NO ISSUES OBSERVED**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 435984 Type: WELL API Number: 017-07782 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, BATTERY 1200' E @ 38.863970,-102.362950

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: QUINT, CRAIG

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: CRP

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: QUINT, CRAIG

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: CRP _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Berms | Pass | | | | | |

S/A/V: SATISFACTOR Y _____

Corrective Date: _____

Comment: **EROSION STARTING AT ENTRANCE, INSTALL BMP'S**

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT