

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
06/01/2015

Document Number:  
668501491

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>277584</u>	<u>305007</u>	<u>Welsh, Brian</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>86610</u>
Name of Operator:	<u>CAERUS WASHCO LLC</u>
Address:	<u>600 17TH STREET - STE #1600N</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Sprague, Chuck	970-630-0214	csprague@caerusoilandgas.com	

**Compliance Summary:**

QtrQtr: NWSW Sec: 24 Twp: 2S Range: 44W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/11/2013	668601806	PR	PR	SATISFACTORY	P		No
08/17/2011	200318799	PR	PR	SATISFACTORY			No
03/31/2010	200241293	SR	PR	SATISFACTORY			No
04/23/2008	200130684	PR	PR	<b>ACTION REQUIRED</b>			Yes

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277584	WELL	PR	11/30/2005	GW	125-09253	WELP 13-24	PR <input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	DIRT ROAD THROUGH PASTURE. WILL NEED MAINTENANCE		

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	LEASE SIGN BY WATER TANK		
WELLHEAD	SATISFACTORY	LEASE SIGN BY FENCE AT UNIT		
TANK LABELS/PLACARDS	SATISFACTORY	METAL SIGN BY WATER TANK		

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
STORAGE OF SUPL	SATISFACTORY	PUMP UNIT NEATLY STORED ON LOCATION		

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	METAL PANELS AROUND UNIT, WELLHEAD AND WATER TANK		

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Prime Mover	0	SATISFACTORY	ARROW GAS ENGINE REMOVED FROM UNIT		
Deadman # & Marked	4	SATISFACTORY			
Pump Jack	1	SATISFACTORY	JENSEN UNIT		
Ancillary equipment	1	SATISFACTORY	GAS SCRUBBER (DISCONNECTED, NOT IN USE)		

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS

PRODUCED WATER	1	OTHER	PBV FIBERGLASS	39.867130,-102.257030	
S/A/V:	SATISFACTORY		Comment: <b>FIBERGLASS WATER TANK 50% BURIED</b>		
Corrective Action:				Corrective Date:	
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)	210BBL				
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					
<b>Venting:</b>					
Yes/No	Comment				
NO					
<b>Flaring:</b>					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

**Predrill**

Location ID: 277584

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** SATISFACTORY **Comment:** NO COA'S

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 277584 Type: WELL API Number: 125-09253 Status: PR Insp. Status: PR

**Producing Well**

**Comment:** PRODUCING. CASING PRODUCTION. CENTRAL METER RUN FOR (WELP 11-24, 12-24, 13-24, 14-24) 1340' N @ 39.87093/-102.25729

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

Inspector Name: Welsh, Brian

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

**Water Well:**

DWR Receipt Num: _____	Owner Name: _____	GPS: _____	Lat _____	Long _____
------------------------	-------------------	------------	-----------	------------

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

Inspector Name: Welsh, Brian

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR  
Y \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

ACCESS HAS MINOR EROSION AND WILL NEED MAINTENANCE

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT