



photo 1: Well sign on the location, GE-20-04.



photo 2: Facing west towards the production equipment.



photo 3: Facing southeast towards the location.



photo 4: Open pit at the west side of the location.



photo 5: Pit approximately 10-15ft. deep has vertical sides that may pose a danger to wildlife.



photo 6: Topsoil pile is not protected from erosion and should be stabilized with vegetation.