

Area of old tank battery excavation



Area of old tank battery; estimated 20'x30'x10' excavation. Approximate location is 40.97974,-108.308731. picture is looking north.




Area of pit id 100601, Approximate size 20' diameter, 15' deep. Approximate location is 40.979746, - 108.308608. Picture is looking north-west. Note; obvious hydrocarbon contamination.



Area of pit described in Remediation project number 8333. Note; erosion at equipment access road. Estimated size is 60 diameter and 60' deep. Picture is facing north.



Soil pile 1 of 2 large piles, appears to be clean fill, operator should confirm what soil is. Approximate location is 40.97982 -108.30908. Picture is facing north-west



Area of old tank battery excavation

Area of pit id 100601, excavation

Picture looking north, slightly north-east