

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/10/2015

Document Number:

668501526

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	206081	321115	Welsh, Brian	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Esquivel, James	620-272-4913	280189@pld.com	

Compliance Summary:QtrQtr: SWSE Sec: 1 Twp: 35S Range: 46W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/14/2014	668602848	IJ	AC	SATISFACTORY	P		No
07/11/2013	668601061	IJ	AC	SATISFACTORY			No
04/30/2013	668600699	IJ	AC	SATISFACTORY			No
07/27/2011	200316368	RT	AC	SATISFACTORY			No
06/22/2010	200257301	RT	AC	SATISFACTORY			No
08/03/2009	200216154	RT	AC	SATISFACTORY			No
02/17/2009	200207499	ES	AC	SATISFACTORY			No
07/16/2008	200193295	MI	AC	SATISFACTORY			No
05/02/2007	200110254	RT	AC	SATISFACTORY		Pass	No
08/01/2006	200094742	RT	AC	SATISFACTORY		Pass	No
02/10/2005	200066930	RT	AC	SATISFACTORY		Pass	No
08/10/2004	200058067	RT	AC	SATISFACTORY		Pass	No
07/29/2003	900970	MI	AC	SATISFACTORY		Pass	No
08/08/2002	200029678	RT	AC	SATISFACTORY		Pass	No
08/23/2001	200019485	RT	AC	SATISFACTORY		Pass	No
02/23/2001	200015406	RT	AC	SATISFACTORY	I	Pass	No
03/03/2000	200005083	RT	AC	SATISFACTORY	I	Pass	No
05/04/1999	500136475	RT	AC	SATISFACTORY		Pass	No
05/04/1999	500136476	RT	AC	SATISFACTORY		Pass	No
06/11/1998	500136474	RT	AC	SATISFACTORY		Pass	No

Inspector Name: Welsh, Brian

02/13/1997	500136473	RT	AC	SATISFACTORY		Pass	No
------------	-----------	----	----	--------------	--	------	----

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
150420	UIC ENHANCED RECOVERY	AC	07/18/1997		-	LANSING D SAND UNIT	AC	<input type="checkbox"/>
206081	WELL	IJ	05/01/1999	ERIW	009-06497	S E CAMPO UNIT/LANSING D 1202W/302W	IJ	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	GRAVEL ROADOFF OF COUNTY ROAD C.00		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY	STICKER ON CHEMICAL DRUM		
WELLHEAD	SATISFACTORY	LEASE SIGN BY WELLHEAD		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	PIPE FENCE AROUND ELECTRIC PANEL AND CATHODIC RECTIFIER		

Inspector Name: Welsh, Brian

OTHER	SATISFACTORY	PIPE FENCE AROUND TRANSFORMERS		
WELLHEAD	SATISFACTORY	PIPE FENCE AROUND WELLHEAD		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	8	SATISFACTORY	3- TRANSFORMERS, WELLHEAD W/WATER METER, CATHODIC RECTIFIER, ELEC PANEL, CHEMICAL TANK W/CONTAINMENT& SOLAR POWERED PUMP		

Facilities:

☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	37.031760,-102.549700
S/A/V:		Comment:	CENTRAL BATTERY 4300' N	
Corrective Action:				Corrective Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 206081

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** SATISFACTORY **Comment:** NO COA'S**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 206081 Type: WELL API Number: 009-06497 Status: IJ Insp. Status: IJ

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg -16" HG Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LSNGD

TC: Pressure or inches of Hg 0 PSIG Previous Test Pressure _____ Last MIT: 07/11/2013

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: NO

Comment: CASING HAD A LIGHT PUFF THAT DIED IMMEDIATELY, TBG IJ @ -16" HG

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	MHSP	Pass	

Inspector Name: Welsh, Brian

Compaction	Pass	Compaction	Pass			
------------	------	------------	------	--	--	--

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT