



Photo 1. View of musk thistle (*Carduus nutans*) growing around project facilities.



Photo 2. View of well head facing southeastward. Ruderal vegetation such as flixweed (*Descurainia sophia*) and tumble mustard (*Sisymbrium altissimum*) can be observed in the foreground.



Photo 3. View of project area from southeastern corner facing center.



Photo 4. View of surrounding pasture full of ruderal weeds such as flixweed and tumble mustard.