

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/15/2015

Document Number:
668403152

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>259447</u>	<u>316243</u>	<u>BROWNING, CHUCK</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100264</u>
Name of Operator:	<u>XTO ENERGY INC</u>
Address:	<u>382 CR 3100</u>
City:	<u>AZTEC</u> State: <u>NM</u> Zip: <u>87410</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field

Compliance Summary:

Qtr/Sec:	<u>NESE</u>	Sec:	<u>1</u>	Twp:	<u>2S</u>	Range:	<u>97W</u>
----------	-------------	------	----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/09/2015	668402844	IJ	AC	SATISFACTORY	P		No
07/21/2014	668402457	IJ	AC	SATISFACTORY	P		No
07/16/2013	669300698	IJ	AC	SATISFACTORY	P		No
10/24/2012	669300224	IJ	AC	SATISFACTORY			No
04/28/2010	200245285	MI	SI	SATISFACTORY			No

Inspector Comment:

Routine UIC Inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159328	UIC DISPOSAL	AC	01/14/2010		-	PICEANCE CREEK UNIT T86X-1G	AC	<input checked="" type="checkbox"/>
259447	WELL	IJ	09/28/2012	GW	103-10096	PICEANCE CREEK UNIT T86X-1G	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 259447

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 159328 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: 480

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) _____ Inj Zone: _____

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTRReq: _____

Comment: **Routine UIC Inspection. No active injection at time of inspection.**

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Facility ID: 259447 Type: WELL API Number: 103-10096 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 159 Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) _____ Inj Zone: WSTCA

TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 04/28/2010

Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTRReq: _____

Comment: **Routine UIC Inspection. No active injection at time of inspection.**

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Inspector Name: BROWNING, CHUCK

Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	SI	Pass	

S/A/V: SATISFACTOR Corrective Date: _____
Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT