

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
06/17/2015

Document Number:
673901006

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|--------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>246146</u> | <u>326966</u> | <u>Rains, Bill</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|--|
| OGCC Operator Number: | <u>100322</u> |
| Name of Operator: | <u>NOBLE ENERGY INC</u> |
| Address: | <u>1625 BROADWAY STE 2200</u> |
| City: | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|--------------------------------|
| HEATHER, FOGEL | | hfogel@nobleenergyinc.com | send all noble inp. to heather |

Compliance Summary:

QtrQtr: SESE Sec: 1 Twp: 8N Range: 59W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 11/12/2009 | 200223000 | PR | PA | SATISFACTORY | | | No |
| 01/23/2009 | 200203315 | ES | PR | ACTION REQUIRED | | | Yes |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|--|
| 246146 | WELL | PR | 01/01/2011 | GW | 123-13943 | LILLI UNIT 16-1 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|------------------------------|--------------------------------------|---------------------------------------|-------------------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | ACTION REQUIRED | No content sign on production tanks. | Install sign to comply with rule 210. | 07/17/2015 |

Inspector Name: Rains, Bill

| | | | |
|------------|--------------|--|--|
| WELLHEAD | SATISFACTORY | | |
| BATTERY | SATISFACTORY | | |
| CONTAINERS | SATISFACTORY | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------------|------------------------------|--|-------------------|---------|
| SEPARATOR | SATISFACTORY | Wire | | |
| TANK BATTERY | SATISFACTORY | Wire | | |
| IGNITOR/COMBUST OR | SATISFACTORY | Wire | | |
| PIT | SATISFACTORY | It has been reclaimed but sin still remains in wire. | | |
| PUMP JACK | SATISFACTORY | Wire | | |
| WELLHEAD | SATISFACTORY | Wire | | |

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-------------------------|---|------------------------------|------------|-------------------|---------|
| Veritcal Heater Treater | 1 | SATISFACTORY | | | |
| Pump Jack | 1 | SATISFACTORY | | | |
| Emission Control Device | 1 | SATISFACTORY | | | |
| Bird Protectors | 2 | SATISFACTORY | | | |
| Gas Meter Run | 1 | SATISFACTORY | | | |
| Ancillary equipment | 1 | SATISFACTORY | Chem tank | | |
| Prime Mover | 1 | SATISFACTORY | Ajax motor | | |
| Vertical Separator | 1 | SATISFACTORY | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|---------------------|--------|
| | | | CENTRALIZED BATTERY | , |

S/A/V: _____ Comment: **Battery facilitating Lilli units 10-1,16-1,8-1,6-1,2-1**

Corrective Action: _____ Corrective Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

| <u>Berms</u> | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|----------|----------|-----------------|------------------|
| | | | CENTRALIZED PAD | |
| S/A/V: | Comment: | | | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|------------------|-------|
| Condition | |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|----------------------------|-----------|-------------|------------------|
| PRODUCED WATER | 1 | <100 BBLS | BV CONCRETE | |
| S/A/V: | SATISFACTORY Comment: | | | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|------------------|-------|
| Condition | |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|----------------------------|----------|-----------|-----------------------|
| CRUDE OIL | 4 | 400 BBLS | STEEL AST | 40.684400,-103.916650 |
| S/A/V: | SATISFACTORY Comment: | | | |
| Corrective Action: | | | | Corrective Date: |

Paint

Inspector Name: Rains, Bill

| | | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|--|
| Condition | Adequate | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | |
|-----------------|---------|
| Venting: | |
| Yes/No | Comment |
| NO | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 246146

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 246146 Type: WELL API Number: 123-13943 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

BradenHead

Comment: Bradenhead exposed to surface.

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Inspector Name: Rains, Bill

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): Y
 Comment: _____
 Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: Rains, Bill

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | MHSP | Pass | |

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)