

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

06/17/2015

Document Number:

678300227

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 283194 | 333368 | GINTAUTAS, PETER | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 1401 17TH ST STE 1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|------------------------|-----------------|
| Hiss, Duane | | duane.hiss@pxd.com | |
| Webb, Julie | | julie.webb@pxd.com | all inspections |
| White, LaCretia | | lacretia.white@pxd.com | all inspections |
| Gillen, Katie | | kathryn.gillen@pxd.com | all inspections |

Compliance Summary:

| | | | | | | | |
|---------------------|-----------|----------------|-----------------|-------------------------------|----------|----------------|-----------------|
| QtrQtr: <u>NESW</u> | | Sec: <u>16</u> | Twp: <u>32S</u> | Range: <u>67W</u> | | | |
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 11/27/2012 | 668200343 | PR | PR | SATISFACTORY | I | | No |
| 08/24/2010 | 200273630 | PR | PR | SATISFACTORY | | | No |
| 01/29/2007 | 200103744 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|-------------------------------------|
| 283194 | WELL | PR | 07/12/2007 | GW | 071-08709 | BRIANNA 23-16 | EI | <input checked="" type="checkbox"/> |
| 285200 | PIT | CL | 08/02/2012 | | - | BRIANNA 23-16 | CL | <input type="checkbox"/> |
| 300636 | WELL | AL | 04/12/2011 | LO | 071-09731 | BRIANNA 23-16 TR | AL | <input type="checkbox"/> |

Equipment:Location Inventory

Inspector Name: GINTAUTAS, PETER

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| Main | SATISFACTORY | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|----------------|------|-----------|---|------------|
| Produced Water | | <= 5 bbls | observed water leaking at pumpjack and called James Roybal. Operator came to well as I left and made repairs. Spill not of reprotable quantity. | 06/17/2015 |

☐ Multiple Spills and Releases?

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------------|---|------------------------------|--|-------------------|---------|
| Vertical Separator | 1 | SATISFACTORY | | | |
| Deadman # & Marked | 4 | SATISFACTORY | | | |
| Gas Meter Run | 1 | SATISFACTORY | meter in shed | | |
| Pump Jack | 1 | SATISFACTORY | see spill comment above and attached photo | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| NO | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 283194

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 283194 Type: WELL API Number: 071-08709 Status: PR Insp. Status: EI

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

| | | |
|--------------------------------------|--|-------------|
| | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |
| Field Parameters: | | |
| | | |
| Sample Location: _____ | | |
| | | |
| Emission Control Burner (ECB): _____ | | |
| Comment: _____ | | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Ditches | Pass | | | | | |
| Sediment Traps | Pass | | | | | |

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: _____ Pit ID: 285208 Lat: 37.170870 Long: -104.865100

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____

Oil Accumulation: _____

2+ feet Freeboard: _____

Pit (S/A/V): SATISFACTOR

Comment: pit closed per approved remediation

Corrective Action: _____

Date: _____

Inspector Name: GINTAUTAS, PETER

| | | | |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
| | 285200 | 1395511 | |
| | 285200 | 1395511 | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 678300228 | spill | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3629138 |