

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
06/18/2015

Document Number:
673710681

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|-----------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>422694</u> | <u>422708</u> | <u>Sherman, Susan</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|--|
| OGCC Operator Number: | <u>19160</u> |
| Name of Operator: | <u>CONOCO PHILLIPS COMPANY</u> |
| Address: | <u>P O BOX 2197</u> |
| City: | <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77252-</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|---------------------------------------|--------------------------|
| Strickler, Robert | | Robert.D.Strickler@conocophillips.com | All DJ Basin Inspections |
| Gahr, Dean | (303) 268-3723 | Dean.P.Gahr@conocophillips.com | All DJ Basin Inspections |
| Savage, Ali | (281) 260-5359 | ali.savage@conocophillips.com | |

Compliance Summary:

QtrQtr: NENE Sec: 32 Twp: 4S Range: 64W

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 422694 | WELL | AL | 02/15/2012 | LO | 005-07164 | Tebo 32-1H | AL | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|--------------------------------------|--------------------------------|----------------------------|---------------------------------|
| Special Purpose Pits: <u> </u> | Drilling Pits: <u> </u> | Wells: <u> 1 </u> | Production Pits: <u> </u> |
| Condensate Tanks: <u> </u> | Water Tanks: <u> 2 </u> | Separators: <u> 2 </u> | Electric Motors: <u> 1 </u> |
| Gas or Diesel Mortors: <u> </u> | Cavity Pumps: <u> 2 </u> | LACT Unit: <u> </u> | Pump Jacks: <u> 1 </u> |
| Electric Generators: <u> 1 </u> | Gas Pipeline: <u> 1 </u> | Oil Pipeline: <u> 1 </u> | Water Pipeline: <u> </u> |
| Gas Compressors: <u> </u> | VOC Combustor: <u> 1 </u> | Oil Tanks: <u> 3 </u> | Dehydrator Units: <u> </u> |
| Multi-Well Pits: <u> </u> | Pigging Station: <u> </u> | Flare: <u> 1 </u> | Fuel Tanks: <u> </u> |

Location

Emergency Contact Number (S/AV): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills: _____

Inspector Name: Sherman, Susan

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

Multiple Spills and Releases?

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 422694

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: SATISFACTORY **Comment:** not drilled

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 422694 Type: WELL API Number: 005-07164 Status: AL Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: DRY LAND, RANGELAND
 Comment:
 1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____
 1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Inspector Name: Sherman, Susan

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: DRY LAND, RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built Pass

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: Fondis-Colby silt loam soil type

Corrective Action: _____

Date _____

Overall Final Reclamation Pass

Well Release on Active Location

Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| Form 4, #2331549 dated 2/6/2012 was approved by COGCC 2/15/2012. | ShermaSe | 06/20/2015 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 673710705 | Conoco Phillips Company Tebo 32-1H AL | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3629404 |