

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/24/2015

Document Number:

671104134

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	269876	332047	MONTOYA, JOHN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 3801-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Helgeland, Gary		gary.helgeland@state.co.us	
Forma, Joe	1-800-291-1969	joeobenergy@aol.com	

Compliance Summary:

QtrQtr: <u>SWNW</u>		Sec: <u>21</u>	Twp: <u>3N</u>	Range: <u>62W</u>			
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/17/2008	200199767	PR	PR	SATISFACTORY			No
12/18/2006	200101501	PR	PR	ACTION REQUIRED		Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
269876	WELL	SI	04/16/2015	GW	123-21760	LOST CREEK 14	SI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Inspector Name: MONTOYA, JOHN

BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	SE CORNER ROD IRON FENCE N40.12780W-104.20136		
SEPARATOR	SATISFACTORY	SE CORNER BARBWIRE N40.12789W-104.20120		
TANK BATTERY	SATISFACTORY	SE CORNER BARBWIRE FENCE N40.12792-104.20108		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	1	SATISFACTORY	SE CORNER N40.12789W-104.20120	-	
Plunger Lift	1	SATISFACTORY			
Bird Protectors	1	SATISFACTORY	SE CORNER N40.12789W-104.20120		

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS	,

S/A/V: SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action: _____ Corrective Date: _____

Comment				
Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.127920,-104.201080
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:
Paint				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) _____				
Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				
Venting:				
Yes/No		Comment		
Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 269876

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 269876 Type: WELL API Number: 123-21760 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: MONTOYA, JOHN

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<u>Water Well:</u>			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
<u>Field Parameters:</u>			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
Comment:

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: MONTOYA, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD	montoyaj	06/24/2015