



photo 1: Beginning near New Elk 27-08 facing south along the access road towards New Elk 26-05.



photo 2: Access road facing south towards the location has recently been recontoured and reclaimed.



photo 3: Areas of disturbance along the access road have been hydro seeded and mulched.



photo 4: Facing back towards the northwest along the reclaimed access road.