



**photo 1:** Beginning near New Elk 26-04 facing southwest along the access road towards New Elk 27-08.



**photo 2:** Facing southwest along the access road. Wood brush debris is being piled along the toe of the road cut.





**photo 3:** Facing southwest along the access road which is in process of being recontoured and reclaimed.



**photo 4:** Facing southwest along the access road which is in process of being recontoured and reclaimed.





**photo 5:** Facing back to the north along the access road being recontoured.



**photo 6:** Facing south along the recontoured access road.





**photo 7:** Facing back to the north along the access road being recontoured.



**photo 8:** Facing south at the New Elk 27-08 location.





**photo 9:** Noticed a small patch (~20 plants) of Canada thistle growing near on the location.



**photo 10:** Canada thistle growing next to the relaimed access road at Lat/Long: 37.14518,-104.97583.