



photo 1: New Elk 30-05



photo 2: Facing northwest towards the location from the access road.



photo 3: East side of the location is predominately weeds (kochia).



photo 4: Close up picture of Kochia growth.



photo 5: West side of the location has minimal vegetation growth.



photo 6: Facing north at the west side of the location.



photo 7: Soil stockpile located at the west side of the location.



photo 8: Weed growth covering the soil stock pile (Field bindweed, kochia).



photo 9: West side of the location facing east.



photo 10: Noticed Scotch thistle growing at the west side of the location.