

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/23/2015

Document Number:
668303660

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>224895</u>	<u>313701</u>	<u>SCHURE, KYM</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10203</u>
Name of Operator:	<u>BLACK RAVEN ENERGY INC</u>
Address:	<u>165 S UNION BLVD SUITE 410</u>
City:	<u>LAKEWOOD</u> State: <u>CO</u> Zip: <u>80228</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Alstadt, J.		jaldstadt@enerjexresources.com	

Compliance Summary:

QtrQtr: NESW Sec: 13 Twp: 1N Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/03/2014	668303061	IJ	AC	SATISFACTORY			No
04/21/2014	667200004	IJ	AC	SATISFACTORY			No
07/24/2013	668200542	SI	AC	SATISFACTORY	P		No
08/27/2012	663400800	SI	SI	SATISFACTORY	P		No
07/19/2011	200315567	RT	SI	ACTION REQUIRED			Yes
08/05/2010	200265950	RT	AC	SATISFACTORY			No
06/05/2009	200211728	RT	SI	SATISFACTORY			No
04/09/2008	200130273	RT	AC	SATISFACTORY			No
08/14/2007	200117873	MI	AC	SATISFACTORY			No
08/04/2006	200094734	RT	AC	SATISFACTORY		Pass	No
06/03/2005	200072621	RT	AC	SATISFACTORY		Pass	No
06/30/2004	200056294	RT	AC	SATISFACTORY		Pass	No
05/05/2004	200054118	RT	AC	SATISFACTORY		Pass	No
05/08/2003	200038578	RT	AC	SATISFACTORY		Pass	No
05/14/2002	200027379	MI	AC	SATISFACTORY		Pass	No
04/11/2002	200026672	RT	AC	SATISFACTORY		Pass	No
08/15/2001	200022409	RT	AC	SATISFACTORY		Pass	No
08/17/2000	200009453	RT	AC	SATISFACTORY		Pass	No

Inspector Comment:

UIC ROUTINE INSPECTION

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
224895	WELL	IJ	10/31/2013	SI	087-05288	CLAR, L 2	SI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY			

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	0	SATISFACTORY			

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 224895

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 224895 Type: WELL API Number: 087-05288 Status: IJ Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 _____
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____ MPP _____
Inj Zone: DSND

TC: Pressure or inches of Hg 0 _____

Previous Test Pressure _____ Last MIT: 08/27/2012

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____ AnnMTReq: _____

Comment: No pressure on casing upon valve opening.

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: No problems found.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

S/A/V: SATISFACTOR
Y _____ Corrective Date: _____

Comment: Continue BMP's for stormwater erosion control and maintenance. No problems observed.

CA: _____

Pits: NO SURFACE INDICATION OF PIT