



02469561

05-067-08721

Loc # 333647

IID 1016
entered 5/6/03**Domestic Water Well Test Research for Water Well Testing per Infill Order 112-156 and 112-157 La Plata County Colorado**3/16/2003
DATE031603-1
FCGNO
BLMRowena 34-8 # 25-2
Gas Well NameNWNE Sec 25 T34N R8W
LocationGasWellDavis D. Dunagan (Posttest)
NAME10623 HWY172 Ignacio, Co 81137
AddressWaterWell
Same
MailingAddress970-884-6075
TELEPHONE**Water Well Location and Permit Information**81822

WaterWellPermit#

NE
QTRQTR25
SECTION34
TWP North8
Range West47
WELLDEPTH23
STATICWATE-107.66287
LONG37.16798
LATITUDE**No analysis for below parameters-Water well went dry per owner.**

Contact Davis. Hauling water well went dry and may or may not pull pump. May drill new well later. NO POSTTEST- WELL DRIED UP PER OWNER. SEND NOTIFICATION TO STATE FOR COMPLIANCE.

COMMENTS

Four Corners Geoscience conducted onsite field chemistries, observation of physical characteristics of water while pumping system to receive a fresh aquifer sample. Water samples were collected and delivered to EPA quality assured lab for analysis. Water samples for bacterial analysis were collected and delivered to San Juan Basin Health in Durango, CO. Samples for headspace gas analysis were taken to FCG lab per USGS standard and methods for these analysis. Four Corners Geoscience is not liable for the results of these analysis and recommends referral to specialists in the field or water treatment. All methods are conducted in accordance with the requirements for this groundwater monitoring program in La Plata Colorado per Colorado Oil and Gas Conservation Commission Order # 112-156 and 112-157 established in July 2000. *NO WATER WELL TEST NO WATER WELLS DRILLED