

Federal 6-24

Inspection# 673402196

No sign at battery (sign at wellhead only), annual and noxious weeds on location.



Apparent bird nesting inside separator.



Incomplete tank label.



Ruts on location.



Ruts in access road.



Ruts in access road.

