

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

07/14/2015

Document Number:

666801129

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	279901	335160	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

**Compliance Summary:**QtrQtr: SWSE Sec: 16 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/06/2015	666800621	PR	PR	<b>ACTION REQUIRED</b>			No
03/17/2010	200239347	PR	PR	SATISFACTORY			No
04/14/2007	200115178	PR	PR	SATISFACTORY	I	Pass	No

**Inspector Comment:**Action required items noted on previous inspection have been satisfied**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
211107	WELL	PR	11/07/1994	GW	045-06866	CLOUGH RMV 4-16	PR	<input checked="" type="checkbox"/>
279769	WELL	PR	04/27/2007	GW	045-11084	CLOUGH RWF 343-16	PR	<input checked="" type="checkbox"/>
279896	WELL	PR	04/27/2007	GW	045-11095	CLOUGH RWF 433-16	PR	<input checked="" type="checkbox"/>
279897	WELL	PR	04/27/2007	GW	045-11096	CLOUGH RMV 164-16	PR	<input checked="" type="checkbox"/>
279899	WELL	PR	04/27/2007	GW	045-11097	CLOUGH RWF 431-21	PR	<input checked="" type="checkbox"/>
279901	WELL	PR	04/27/2007	GW	045-11098	CLOUGH RWF 534-16	PR	<input checked="" type="checkbox"/>
279903	WELL	PR	07/31/2008	GW	045-11099	CLOUGH RWF 33-16	PR	<input checked="" type="checkbox"/>
279904	WELL	PR	04/27/2007	GW	045-11100	CLOUGH RMV 151-21	PR	<input checked="" type="checkbox"/>
279907	WELL	PR	04/27/2007	GW	045-11101	CLOUGH RWF 434-16	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

279908	WELL	PR	08/18/2008	GW	045-11103	CLOUGH RWF 541-21	PR	<input checked="" type="checkbox"/>
279909	WELL	PR	07/31/2008	GW	045-11102	CLOUGH RWF 334-16	PR	<input checked="" type="checkbox"/>
279910	WELL	PR	04/27/2007	GW	045-11104	CLOUGH RWF 333-16	PR	<input checked="" type="checkbox"/>
279911	WELL	PR	04/27/2007	GW	045-11105	CLOUGH RWF 344-16	PR	<input checked="" type="checkbox"/>
279912	WELL	PR	04/27/2007	GW	045-11106	CLOUGH RWF 543-16	PR	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	14	SATISFACTORY			
Plunger Lift	14	SATISFACTORY			

**Venting:**

Yes/No	Comment
YES	Bradenhead valves open

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 279901

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 211107 Type: WELL API Number: 045-06866 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 279769 Type: WELL API Number: 045-11084 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 279896 Type: WELL API Number: 045-11095 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID:	279897	Type:	WELL	API Number:	045-11096	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279899	Type:	WELL	API Number:	045-11097	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279901	Type:	WELL	API Number:	045-11098	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279903	Type:	WELL	API Number:	045-11099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279904	Type:	WELL	API Number:	045-11100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279907	Type:	WELL	API Number:	045-11101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279908	Type:	WELL	API Number:	045-11103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279909	Type:	WELL	API Number:	045-11102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279910	Type:	WELL	API Number:	045-11104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279911	Type:	WELL	API Number:	045-11105	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Facility ID:	279912	Type:	WELL	API Number:	045-11106	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Environmental									

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Inspector Name: Murray, Richard

Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Sediment Traps	Pass					
Seeding	Pass					
Gravel	Pass					
Ditches	Pass					
Slope Roughening	Pass					
		Ditches	Pass			

S/A/V: SATISFACTOR \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT