

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/15/2015

Document Number:
666801134

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>272540</u>	<u>335109</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>1001 17TH STREET - SUITE #1200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

Compliance Summary:

QtrQtr: SENE Sec: 19 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/03/2010	200285716	PR	PR	SATISFACTORY			No
03/15/2010	200235297	PR	PR	SATISFACTORY			No
11/10/2005	200085094	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
257741	WELL	PR	06/20/2000	GW	045-07594	FEDERAL RMV 144-19	PR	<input checked="" type="checkbox"/>
272540	WELL	PR	11/20/2004	GW	045-10097	FEDERAL RWF 342-19	PR	<input checked="" type="checkbox"/>
272541	WELL	PR	11/22/2004	GW	045-10096	FEDERAL RWF 442-19	PR	<input checked="" type="checkbox"/>
286363	WELL	PR	08/24/2006	GW	045-12651	FEDERAL RWF 432-19	PR	<input checked="" type="checkbox"/>
286364	WELL	PR	08/24/2006	GW	045-12650	FEDERAL RWF 32-19	PR	<input checked="" type="checkbox"/>
286365	WELL	PR	08/24/2006	GW	045-12649	FEDERAL RWF 532-19	PR	<input checked="" type="checkbox"/>
286366	WELL	PR	08/24/2006	GW	045-12648	FEDERAL RWF 332-19	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-0596-002		

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	10	SATISFACTORY			
Plunger Lift	7	SATISFACTORY			

Venting:	
Yes/No	Comment
YES	Bradenhead valves open

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 272540

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 257741 Type: WELL API Number: 045-07594 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 272540 Type: WELL API Number: 045-10097 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 272541 Type: WELL API Number: 045-10096 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 286363 Type: WELL API Number: 045-12651 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 286364 Type: WELL API Number: 045-12650 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 286365 Type: WELL API Number: 045-12649 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 286366 Type: WELL API Number: 045-12648 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____
 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Culverts	Pass					
		Ditches	Pass			
Rip Rap	Pass					Will need maintenance
Seeding	Pass					
Berms	Pass					
Ditches	Pass					
		Culverts	Pass			
		Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT