

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
07/15/2015

Document Number:  
675201781

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334537</u>	<u>334537</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>66561</u>
Name of Operator:	<u>OXY USA INC</u>
Address:	<u>PO BOX 27757 #110</u>
City:	<u>HOUSTON TX</u> State: <u>TX</u> Zip: <u>77227-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		chris_clark@oxy.com	

**Compliance Summary:**

QtrQtr: SWNW Sec: 17 Twp: 10S Range: 94W

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
100123	PIT	CL	09/23/1999		-	COLORADO LAND 1	CL	<input type="checkbox"/>
221800	WELL	PA	11/05/2013	GW	077-08402	COLORADO LAND 1	PA	<input type="checkbox"/>
292979	WELL	PR	08/18/2010	GW	077-09429	LARAMIE LAND&CATTLE CO 17-6B	PR	<input checked="" type="checkbox"/>
292980	WELL	PR	01/01/2011	GW	077-09428	LARAMIE LAND&CATTLE CO 17-6A	PR	<input checked="" type="checkbox"/>
292981	WELL	PR	04/17/2012	GW	077-09427	LARAMIE LAND&CATTLE CO 17-6	PR	<input checked="" type="checkbox"/>
292982	WELL	PR	05/04/2008	GW	077-09426	LARAMIE LAND&CATTLE CO 17-3	PR	<input checked="" type="checkbox"/>
292986	WELL	PR	06/05/2012	GW	077-09425	LARAMIE LAND&CATTLE CO 17-4	PR	<input checked="" type="checkbox"/>
292987	WELL	PR	01/06/2009	GW	077-09424	LARAMIE LAND&CATTLE CO 17-3A	PR	<input checked="" type="checkbox"/>
292988	WELL	PR	09/01/2013	GW	077-09423	LARAMINE LAND&CATTLE CO 17-3B	PR	<input checked="" type="checkbox"/>

292989	WELL	PR	04/17/2008	GW	077-09422	LARAMIE LAND&CATTLE CO 17-3C	PR	<input checked="" type="checkbox"/>
293023	WELL	AL	06/28/2011	LO	077-09430	LARAMIE LAND AND CATTLE 17-6C	AL	<input type="checkbox"/>
293024	WELL	PR	03/17/2009	GW	077-09431	LARAMIE LAND & CATTLE COMPANY 17-4A	PR	<input checked="" type="checkbox"/>
293025	WELL	AL	06/28/2011	LO	077-09432	LARAMIE LAND AND CATTLE 17-5	AL	<input type="checkbox"/>
293026	WELL	AL	06/28/2011	LO	077-09433	LARAMIE LAND AND CATTLE 17-5B	AL	<input type="checkbox"/>
293027	WELL	AL	06/28/2011	LO	077-09434	LARAMIE LAND AND CATTLE 17-5C	AL	<input type="checkbox"/>
293028	WELL	AL	06/28/2011	LO	077-09435	LARAMIE LAND AND CATTLE CO. (LL&CC) 17-4C	AL	<input type="checkbox"/>
293029	WELL	AL	06/28/2011	LO	077-09436	LARAMIE LAND & CATTLE CO. 17-5A	AL	<input type="checkbox"/>
293031	WELL	PR	07/01/2014	GW	077-09437	LARAMIE LAND & CATTLE COMPANY 17-4B	PR	<input checked="" type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD		Nearest public access not listed on signs.		

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: 970-248-0497

Corrective Action: \_\_\_\_\_

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	Wire fence		

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY	Chem units with containments		
Vertical Heated Separator	10	SATISFACTORY			
Plunger Lift	10	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			

<b>Facilities:</b>				
<input type="checkbox"/> New Tank	Tank ID: _____			
Contents	#	Capacity	Type	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST	,
S/AV:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	
Corrective Action				Corrective Date
Comment	Vegetation growing in containment. See attached photo.			

<b>Venting:</b>	
Yes/No	Comment
NO	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 334537

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 292979 Type: WELL API Number: 077-09429 Status: PR Insp. Status: PR

**Producing Well**

Comment: **PR w/ Plunger**

Facility ID: 292980 Type: WELL API Number: 077-09428 Status: PR Insp. Status: PR

**Producing Well**

Comment: **PR w/ Plunger**

Facility ID: 292981 Type: WELL API Number: 077-09427 Status: PR Insp. Status: PR

**Producing Well**

Comment: **PR w/ Plunger**

Facility ID: 292982 Type: WELL API Number: 077-09426 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 292986 Type: WELL API Number: 077-09425 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 292987 Type: WELL API Number: 077-09424 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 292988 Type: WELL API Number: 077-09423 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 292989 Type: WELL API Number: 077-09422 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 293024 Type: WELL API Number: 077-09431 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

Facility ID: 293031 Type: WELL API Number: 077-09437 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR w/ Plunger

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS: \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Inspector Name: CONKLIN, CURTIS

Access Roads      Regraded \_\_\_\_\_      Contoured \_\_\_\_\_      Culverts removed \_\_\_\_\_  
 Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_      Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_      Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_      Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_      Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_      Date \_\_\_\_\_

Overall Final Reclamation      Well Release on Active Location       Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			
Seeding	Pass					
Compaction	Pass	Culverts	Pass			
Drains	Pass	Gravel	Pass			

S/A/V: SATISFACTOR      Corrective Date: \_\_\_\_\_  
 Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Nearest public access needs to be listed on signs to comply with 210 rule. Use BMPs to remove and prevent vegetation growth in tank containment.	conklinc	07/15/2015

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675201782	Signs missing nearest public access	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3643210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3643210</a>
675201783	Vegetation in tank containment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3643211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3643211</a>