

**Federal 26-12-89-1**

Inspection# 673402239

Full sediment traps causing erosion on access road.



Full sediment traps with erosion. (Hard hat shown for scale of gullies.)

