



photo 1: Tank battery sign found leaning against the tank.



photo 2: Tank battery sign found leaning against the tank.



photo 3: Facing towards the location from the access road.



photo 4: Northwest side of the location. Weeds (Musk thistle) found growing around the location.



**photo 5:** Northwest side of the location. Weeds (Musk thistle) found growing around the location.



**photo 6:** Musk thistle (List B noxious weed) growing around tank battery location.



**photo 7:** Canada thistle found growing at the northeast side of the location.



**photo 8:** Canada thistle (List B noxious weed) growing around the tank battery location.



photo 9: Facing northwest, weeds growing around the location next to a cultivated field.



photo 10: Interim reclamation area is predominately weed growth.



photo 11: Facing south at the northeast corner of the location. Erosion is transporting sediment off site.



photo 12: Facing southwest towards the location.