



photo 1: Facing northeast towards the location.



photo 2: Facing northeast towards area with sparse vegetation and pipe riser in upper right of photo.



photo 3: Facing east at the location. Pipe risers have not been removed.



photo 4: Facing north at the location. Pipe risers have not been removed.



photo 5: Southeast side of the location. Steel box has not been removed



photo 6: Facing northeast towards the location. Pipe riser can be seen in the distance Steel box has not been removed