

**South Shale Ridge 5-21**

Inspection# 675201795

Soil pile with staining that is not fully contained.



Soil pile with staining that is not fully contained.



Debris from weed mitigation  
around equipment.

