

South Shale Ridge 9-22

Inspection# 675201797

Wellhead sign has been added since previous inspection.



Weed mitigation around equipment. Debris near pump jack.

