

South Shale Ridge 5-23

Inspection# 675201799

Wellhead sign has been
added since previous
inspection.



Weed mitigation around
equipment.



No leaking around wellhead at
time of inspection.

