

South Shale Ridge 9-17

Inspection# 675201801

Wellhead sign has been
added since previous
inspection.



Weed mitigation around
equipment.



No evidence of active leaking
around wellhead.

