

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/22/2015

Document Number:
674102485

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>299237</u>	<u>333299</u>	<u>Rickard, Jeff</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>47120</u>
Name of Operator:	<u>KERR MCGEE OIL & GAS ONSHORE LP</u>
Address:	<u>P O BOX 173779</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Avant, Paul		Paul.Avant@Anadarko.com	Anadarko Inspections
Ready, Luke		luke.reddy@anadarko.com	
, General		COGCCinspections@Anadarko.com	All Inspections, send to Paul Avant as well

Compliance Summary:

QtrQtr:	<u>NWSE</u>	Sec:	<u>12</u>	Twp:	<u>5N</u>	Range:	<u>68W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/19/2010	200279065	SR	AL	SATISFACTORY	P	Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
299235	WELL	AL	03/16/2010	LO	069-06358	MIRACLE 14-12	AL	<input checked="" type="checkbox"/>
299237	WELL	AL	03/16/2010	LO	069-06359	MIRACLE 13-12	AL	<input checked="" type="checkbox"/>
299253	WELL	AL	03/16/2010	LO	069-06360	MIRACLE 19-12	AL	<input checked="" type="checkbox"/>
299254	WELL	AL	03/16/2010	LO	069-06361	MIRACLE 11-12	AL	<input checked="" type="checkbox"/>
299257	WELL	AL	03/16/2010	LO	069-06362	MIRACLE 12-12	AL	<input checked="" type="checkbox"/>
299258	WELL	AL	03/16/2010	LO	069-06363	MIRACLE 10-12	AL	<input checked="" type="checkbox"/>
299259	WELL	AL	03/16/2010	LO	069-06364	MIRACLE 7-12	AL	<input checked="" type="checkbox"/>
299495	WELL	AL	03/16/2010	LO	069-06381	MIRACLE 24-12	AL	<input checked="" type="checkbox"/>
417945	WELL	PR	03/07/2012	OW	069-06405	MIRACLE 7-12	PR	<input type="checkbox"/>

417952	WELL	PR	02/19/2011	OW	069-06406	MIRACLE 11-12	PR	<input type="checkbox"/>
417958	WELL	PR	02/11/2011	OW	069-06407	MIRACLE 10-12	PR	<input type="checkbox"/>
418085	WELL	PR	04/14/2011	OW	069-06409	MIRACLE 12-12	PR	<input type="checkbox"/>
418086	WELL	PR	05/14/2012	OW	069-06410	MIRACLE 15-12	PR	<input type="checkbox"/>
418087	WELL	PR	03/14/2012	OW	069-06411	MIRACLE 14-12	PR	<input type="checkbox"/>
418088	WELL	PR	03/01/2011	OW	069-06412	MIRACLE 23-12	PR	<input type="checkbox"/>
418104	WELL	PR	02/22/2011	OW	069-06416	MIRACLE 19-12	PR	<input type="checkbox"/>
418106	WELL	PR	02/18/2011	OW	069-06418	MIRACLE 13-12	PR	<input type="checkbox"/>
418297	WELL	PR	03/01/2011	OW	069-06426	MIRACLE 22-12	PR	<input type="checkbox"/>
418301	WELL	PR	02/19/2011	OW	069-06427	MIRACLE 25-12	PR	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>11</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>2</u>	Separators: <u>11</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>8</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: <u>11</u>

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 299237

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	glasgowp	Location may be in a sensitive area due to shallow groundwater; therefore if drilling pits intercept groundwater the pit must be lined or a closed loop system used.	06/22/2010

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 299235 Type: WELL API Number: 069-06358 Status: AL Insp. Status: AL

Facility ID: 299237 Type: WELL API Number: 069-06359 Status: AL Insp. Status: AL

Facility ID: 299253 Type: WELL API Number: 069-06360 Status: AL Insp. Status: AL

Facility ID: 299254 Type: WELL API Number: 069-06361 Status: AL Insp. Status: AL

Facility ID: 299257 Type: WELL API Number: 069-06362 Status: AL Insp. Status: AL

Facility ID: 299258 Type: WELL API Number: 069-06363 Status: AL Insp. Status: AL

Facility ID: 299259 Type: WELL API Number: 069-06364 Status: AL Insp. Status: AL

Facility ID: 299495 Type: WELL API Number: 069-06381 Status: AL Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):
Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:
Land Use: IRRIGATED
Comment:
1003a. Debris removed? CM CA Date
Waste Material Onsite? CM CA Date
Unused or unneeded equipment onsite? CM CA Date
Pit, cellars, rat holes and other bores closed? CM CA Date
Guy line anchors removed? CM CA Date
Guy line anchors marked? CM

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: AL's not drilled on active location

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

