



**photo 1:** Facing south towards the location along ranch road that goes near the location.



**photo 2:** Facing south towards the location.



**photo 3:** Center of location facing north.



**photo 4:** Center of location facing west.



**photo 5:** Center of location facing south.



**photo 6:** Center of location facing east.



**photo 7:** Weeds (Russian thistle) found growing throughout the location.



**photo 8:** Weeds (Kochia) found growing throughout the location.



**photo 9:** Debris found at the south side of the dirt pile.



**photo 10:** Wood board debris found at the west side of the dirt pile.



**photo 11:** Facing west at the surrounding vegetation.



**photo 12:** Facing east at the surrounding vegetation.