

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/22/2015

Document Number:
673802343

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>238640</u>	<u>317511</u>	<u>Gomez, Jason</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>82470</u>
Name of Operator:	<u>STELBAR OIL CORP INC</u>
Address:	<u>1625 N WATERFRONT PKWY #200</u>
City:	<u>WICHITA</u> State: <u>KS</u> Zip: <u>67206-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Blaggrave, Bill	316-285-2867	bblaggrave@stelbar.com	
Woodworth, Ty		twoodworth@gwogco.com	

Compliance Summary:

QtrQtr: SESW Sec: 27 Twp: 8N Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/21/2014	673800911	IJ	IJ	SATISFACTORY	P		No
09/17/2013	671100407	IJ	AC	SATISFACTORY			No
08/06/2012	665400340	IJ	AC	SATISFACTORY	P		No
06/27/2011	200313811	RT	AC	SATISFACTORY			No
07/26/2010	200263703	MI	AC	SATISFACTORY			No
07/08/2009	200214305	RT	AC	SATISFACTORY			No
06/08/2009	200214304	RT	AC	SATISFACTORY			No
06/11/2008	200190906	RT	AC	SATISFACTORY			No
08/28/2007	200118060	RT	AC	SATISFACTORY			No
06/12/2006	200091258	RT	AC	SATISFACTORY		Pass	No
08/02/2005	200074462	MI	AC	SATISFACTORY		Pass	No
07/30/2004	200057476	RT	AC	SATISFACTORY		Pass	No
08/26/2003	200043065	RT	AC	SATISFACTORY		Pass	No
08/23/2002	200030695	RT	AC	SATISFACTORY		Pass	No
06/27/2001	200022951	RT	AC	SATISFACTORY		Pass	No
05/15/2000	200006606	MI	AC	SATISFACTORY		Pass	No
03/15/2000	200004955	PR	WO	SATISFACTORY		Pass	No
10/09/1996	500160481	PR	SI			Pass	No
04/20/1996	500160480	MT	SI				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
238640	WELL	IJ	05/15/2000	ERIW	123-05503	KENNEDY 1	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Panel		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Deadman # & Marked	5	SATISFACTORY			

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 238640

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 238640 Type: WELL API Number: 123-05503 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: LYNS

TC: Pressure or inches of Hg _____

Previous Test Pressure _____

Last MIT: 07/26/2010

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____

AnnMTRReq: _____

Comment: _____

Method of Injection: PUMP FEED

Test Type: 5 Year

Tbg psi: 0

Csg psi: 194

BH psi: 0

Insp. Status: Pass

Comment: 1030 psig 5min 1016 psig 10min 1016 psig 15 min 14psig loss

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Inspector Name: Gomez, Jason

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT