



WELL SITE INSPECTION FORM  
(DRILLING AND PLUGGING)

Well Name SE Spargo No. 2 API Number 05 - 033 - 061190  
Operator Ampolex Permit # 92-679  
Location SESW S31-39N-19W County Dolores  
Field \_\_\_\_\_ Inspector M. Weems

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) \_\_\_\_\_ Fail(N) \_\_\_\_\_ Date \_\_\_\_\_ ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_ TA \_\_\_\_\_

=====

Date of Inspection Before/During Drilling 9-12-92

Surf. Csg. Size ? Setting Depth ? Cmt. Vol. ? WOC time ?  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: \_\_\_\_\_ Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bond Release OK: Yes \_\_\_\_\_ No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

Date of Safety/Status Inspection \_\_\_\_\_

Comments: Drilling is complete. Rig is torn down and stacked  
on location incl. misc. components. Well cellar full of water  
& weeds. Too murky to see thru. Rat hole & mouse still  
open. Rsv pit have full of water & mud. Pit is fenced &  
lined. It appears to be D&A.

Violations: Yes \_\_\_\_\_ No ✓ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_