



photo 1: Traveling northwest along main access road towards the location.



photo 2: Traveling northwest along main access road towards the location.



photo 3: Boulders that slid off of the hill along the main access road. Area of concern of the complainant.



photo 4: Boulders that slid off of the hill along the main access road. Area of concern of the complainant.



photo 5: Facing northwest along main access road towards the location.



photo 6: Pipe riser along the main access road. Area of concern of the complainant.



photo 7: Facing souththwest along main access road.



photo 8: Facing northwest along main access road towards the location.



photo 9: Well sign. Outpost 22-24



photo 10: Facing west towards the location.