



photo 1: Well sign. Geri Ann 22-27



photo 2: Facing southwest towards the location.



photo 3: Pit at the west side of the location.



photo 4: Chain indicating 2 ft. freeboard is laying on a flat surface and does not appear to be installed correctly.



photo 5: Fence around the pit is down and not maintained.



photo 6: Unused equipment is left on location.



photo 7: Scotch thistle (list B noxious weed) was found growing at the northwest side of the location.



photo 8: Facing northwest towards the equipment.



photo 9: Southeast side of the location has signs of erosion and sediment trap is filled with sediment.



photo 10: Southeast side of the location has signs of erosion and minimal vegetation growth.