

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/07/2015

Document Number:
674701700

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335905</u>	<u>335905</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:

QtrQtr:	<u>NENW</u>	Sec:	<u>19</u>	Twp:	<u>5S</u>	Range:	<u>95W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/02/2014	663902590			SATISFACTORY	F		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285534	WELL	PR	10/26/2007	GW	045-12514	N. PARACHUTE EF03B19 D19A595	PR	<input checked="" type="checkbox"/>
286632	WELL	PR	01/27/2014	GW	045-12712	N. PARACHUTE EF04A D19A595	PR	<input checked="" type="checkbox"/>
286633	WELL	PR	09/07/2006	GW	045-12711	N. PARACHUTE EF08B D19A 595	PR	<input checked="" type="checkbox"/>
286634	WELL	PR	09/07/2006	GW	045-12710	N.PARACHUTE EF01B D19A 595	PR	<input checked="" type="checkbox"/>
286635	WELL	PR	09/07/2006	GW	045-12709	N. PARACHUTE EF01D D19A 595	PR	<input checked="" type="checkbox"/>
286636	WELL	PR	09/07/2006	GW	045-12708	N. PARACHUTE EF02D D19A 595	PR	<input checked="" type="checkbox"/>
286637	WELL	PR	09/07/2006	GW	045-12707	N.PARACHUTE EF02B D19A 595	PR	<input checked="" type="checkbox"/>
286638	WELL	PR	09/07/2006	GW	045-12706	N. PARACHUTE EF03C D19A 595	PR	<input checked="" type="checkbox"/>
286639	WELL	PR	02/01/2011	GW	045-12705	N. PARACHUTE EF03D D19A 595	PR	<input checked="" type="checkbox"/>
286640	WELL	PR	09/11/2006	GW	045-12704	N. PARACHUTE EF07B D19A 595	PR	<input checked="" type="checkbox"/>

286641	WELL	PR	09/11/2006	GW	045-12703	N. PARACHUTE EF01D-24 D19A 5	PR	<input checked="" type="checkbox"/>
286721	WELL	PR	09/14/2006	GW	045-12772	N. PARACHUTE EF03B D19A 595	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Road work being done on Middle Fork road.		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 800-791-7691

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	3	SATISFACTORY	Chemical containers		
Bird Protectors	1	SATISFACTORY			
Plunger Lift	12	SATISFACTORY			
Gas Meter Run	12	SATISFACTORY	Gas lift		
Gas Meter Run	12	SATISFACTORY			

Facilities:

New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST	,

Inspector Name: LONGWORTH, MIKE

S/A/V:	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
Paint						
Condition	Adequate					
Other (Content)	_____					
Other (Capacity)	80 bbls					
Other (Type)	_____					
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Corrective Action					Corrective Date	
Comment						

Venting:		
Yes/No	Comment	
NO		

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335905

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 285534 Type: WELL API Number: 045-12514 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 286632 Type: WELL API Number: 045-12712 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 286633 Type: WELL API Number: 045-12711 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 286634	Type: WELL	API Number: 045-12710	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286635	Type: WELL	API Number: 045-12709	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286636	Type: WELL	API Number: 045-12708	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286637	Type: WELL	API Number: 045-12707	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286638	Type: WELL	API Number: 045-12706	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286639	Type: WELL	API Number: 045-12705	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286640	Type: WELL	API Number: 045-12704	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286641	Type: WELL	API Number: 045-12703	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Facility ID: 286721	Type: WELL	API Number: 045-12772	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____
 Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				MHSP	Pass	
Seeding		Ditches	Pass			
Berms	Pass					
Gravel	Pass					
		Culverts	Pass			

S/A/V: SATISFACTOR
 Y Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT