

#34-10 #28-2 FC Pipeline Spill August 10, 2015



Figure 1. Valve can that overflowed due to a gas eliminator failure causing 1 bbl of produced water to spill onto the pipeline ROW. A vac truck pulled standing water from the valve can. Spill area is 7' x 7'.



Figure 2. Valve can that overflowed due to a gas eliminator failure causing 2 bbls to spill onto the pipeline ROW and borrow ditch. Spill area is 15' x 5'.