



photo 1: Facing northeast towards location where debris, trash, and concrete slab remains.



photo 2: Various metal debris and concrete slab left at the location.



photo 3: Concrete slab approximately 18'x10'x2' in size.



photo 4: Facing south towards the location.



photo 5: Metal debris found on location.



photo 6: Various debris left at the location.