



photo 1: Facing west along access road towards the location.



photo 2: Facing west towards the location.



photo 3: Well sign Columbine State #1



photo 4: West side of the location facing east.



photo 5: Weeds (Horseweed and Cheatgrass) growing around the wellhead.



photo 6: East side of the location facing west towards the wellhead.



photo 7: Ground view of vegetation near well head. Noticed desirable species of grasses and forbs as well as undesirable weeds.



photo 8: Surrounding vegetation near the location.