

USA Shaw 19

Inspection# 673402366

Overgrown access road.



No wellhead sign, oily fluid in cellar, overgrown location.



Close up of oily fluid in cellar.



Incomplete tank label.
Overgrown berm. Fence
falling down.

