



Photo 1. View of southern portion of project area facing southwestward toward adjacent well pad from southeastern corner. Scotch thistle infestation that was here last season appears to be controlled.



Photo 2. View of vegetation becoming established within the cutslope in the northern portion of the project area. Straw blanket appears to be in good condition.





Photo 3. View from southeastern portion of project area facing center.